
Docket No.: HO-P03194US0


App No.: Not Yet Assigned Dock Inventor: Kevin P. Pearman Title: Wheel Mounted Power Generator

Page 1 of 16

10/540001

Fig. 1






App No.: Not Yet Assigned Inventor: Kevin P. Pearman

Title: Wheel Mounted Power Generator


Page 3 of 16

3/16




Docket No.: HO-P03194US0 10/540001 App No.: Not Yet Assigned Dock Inventor: Kevin P. Pearman Title: Wheel Mounted Power Generator


Page 4 of 16




5/16



Docket No.: HO-P03194US0 10/540001



Page 7 of 16



Docket No.: HO-P03194US0


Page 8 of 16

10/540001

Fig. 8 144 138 0 .152 136 0 0 .130 156 0 606 146 148

Page 9 of 16

9/16



Docket No.: HO-P03194US0 10/540001

App No.: Not Yet Assigned Dock Inventor: Kevin P. Pearman Title: Wheel Mounted Power Generator Page 10 of 16

10/16





Fig. 11



App No.: Not Yet Assigned Inventor: Kevin P. Pearman


Docket No.: HO-P03194US0

10/540001


Title: Wheel Mounted Power Generator

Page 11 of 16

Fig. 12




Page 12 of 16



13/16

Fig. 17



10/540001

App No.: Not Yet Assigned Dock Inventor: Kevin P. Pearman Title: Wheel Mounted Power Generator

Page 14 of 16






Fig. 19



Docket No.: HO-P03194US0


App No.: Not Yet Assigned Dock Inventor: Kevin P. Pearman Title: Wheel Mounted Power Generator Page 15 of 16

Fig. 20



Docket No.: HO-P03194US0 10/540001 App No.: Not Yet Assigned Dock Inventor: Kevin P. Pearman Title: Wheel Mounted Power Generator Page 16 of 16

Fig. 21



This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.